HAB Height Adjustable Base
Installation Instructions


Tools Required

Cylinder Replacement Tool - **7035-4008**


FOR CHAIRS MANUFACTURED **AFTER MAY 1, 2002**.

IF MANUFACTURED **BEFORE MAY 1, 2002,** NEED TO REPLACE CONTROL ASSEMBLY


1 **Assemble chair (A) to base (B)**



2 **Knee chair (A) to seat base (B)**



3 **Snap spindle cover (C) to chair (A)**



CUSTOMER SERVICE PHONE: 1-800-426-8562