ZODY II / Zody LX


Arm Cap, Arm & Arm Assembly Replacement

Installation Instructions

0 1/2 1
1/4 1/4


Scale 1 : 1

Tools Required




ARM CAP REPLACEMENT

1




CUSTOMER SERVICE PHONE: 1-800-426-8562


2



NOTE: Press and hold tab **(B1)** for 20 seconds, then firmly pull arm **(B)** out quickly.

3


C


NOTE: DO NOT use power tools to install screws.
T30
Torque 9.6 N-m
(85 in-lbs)
1
2
C