
ASSEMBLY INSTRUCTION

hushhybrid


HUS-BX-220








ASSEMBLY INSTRUCTIONS


HUS-BX-220






















HUS-BX-220


































HUS-BX-220





Handle body	Handle	Hinge	Push-in fitting	Cable grommet	Cable lock	Clip P
						
x1	x1	x3	x24	x1	x1	x2

Eccentric join Ø35	Connecting bolt M8	M5x35	Screw Ø4x40	M6x55	Wooden dowel	Foot cap	M6x90
							
x26	x26	x6	x12	x4	x2	x4	x1

Black screw Ø4x16	Screw Ø4x16	Screw Ø4x20	M6x14	M5x10	Self locking washer Ø5	M8x16	M6x15
							
x6	x52	x16	x5	x9	x9	x4	x12


SERVICE PACK


x6



x6


x2


x2



NECESSARY TOOLS



PH2




H 3 mm




H 4 mm




H 5 mm



H 6 mm



glass holder




spirit level




knife





pen





drill


















11





12






13




HUS-BX-220























H4


HUS-BX-220





PH2

Connecting bolt M8



x8

Screw Ø4x20




x3


Wooden dowel





x2


HUS-BX-220











PH2 H4

Eccentric join Ø35
x8


Screw Ø4x16
x24


Connecting bolt M8
x8

Push-in fitting
x12

M6x15
x6

HUS-BX-220







Eccentric
join
Ø35



x5

HUS-BX-220








Eccentric
join
Ø35





x5




L












180v




H6

HUS-BX-220








PH2

Screw
Ø4x16




x2


Clip P




x2

HUS-BX-220








PH2

Eccentric join Ø35



x8

Push-in fitting





x12


Screw Ø4x16




x24




L
L







180v



H6

HUS-BX-220






H4/H6


M8x16


x4


M6x15

x2






L






H6









Cable grommet





x1




DRILL OPTIONAL HOLE FOR POWER CABLE











HUS-BX-220






PH2


Screw
Ø4x20


x3


Connecting
bolt M8

x10





L







180v










H6

HUS-BX-220









PH2


Screw
Ø4x16

x3



To pass the power cord the piece of furniture should be lifted














H3














FAN
FACE LED
PIR DRIVER
LED





HUS-BX-220






PH2

Screw
Ø4x16


x2


Cable
lock

x1

















H4






HUS-BX-220








H4


M6x55



x4

HUS-BX-220







H4

M6x15

x4

HUS-BX-220







PH2


Black screw Ø4x16


x3





CABLE GROMMET AND VESA OPTIONAL SELF MADE















OPTIONAL



6 7/8
2 7/32
Surface for
Vesa mount
and grommet
2 7/32
10 5/32
18 1/8
6 7/8
Draw the hole
max Ø 2 51/64
Make this step if u need cable groometa







OPTIONAL


6 7/8
2 7/32
10 5/32
18 1/8
6 7/8
Surface for
Vesa mount
and grommet



Cut a hole
in the desired
location


MAX 2.79’




OPTIONAL






OPTIONAL




M6x90





x1





H4
















HUS-BX-220













Screw
Ø4x20





x10


HUS-BX-220














holder







GLASS



GLASS








HUS-BX-220













HUS-BX-220






PH2


M5x35



x6

HUS-BX-220







PH2


Screw
Ø4x40


x12

HUS-BX-220














HUS-BX-220

























HUS-BX-220













H3/H4

Handle body




x1

Handle




x1


Hinge



x3

HUS-BX-220





H3

M5x10

x9

Self locking washer Ø5

x9

HUS-BX-220

