
HAWORTH


Upside Benching


Recycling & Disassembly Instructions




End of life Upside Benching!








Tools Required



Magnetic Tip




1/8" Drill




3mm
4mm
5mm



Electrical Tape







1 Remove electrical


RECYCLE BINS

STEEL





ELECTRICAL
















2 Remove worksurfaces




TOP VIEW


RECYCLE BINS

STEEL



WOOD







3 Remove power tray

RECYCLE BINS


STEEL



PLASTIC




4 Remove rails




TOP VIEW

RECYCLE BINS

STEEL







5 Remove crossmember


RECYCLE BINS

STEEL






6 Remove bottom tray




7 Remove crossmember from columns





RECYCLE BINS


STEEL













8 Remove feet



9 Remove crossmember from columns



RECYCLE BINS

STEEL

